

Zyxel ZON Utility 2.1.5 C0

Release Note/Manual Supplement

Date: Nov 26, 2020

This document describes the features in the **ZON Utility** for its 2.1.5 C0 release.

Release file list:

File Name	Remark
ZON 2.1.5 C0 Release Note.doc	This file.
Zyxel ZON Utility.exe	Installation file include "ZON utility and ZAC" MD5 checksum is " c633015b987227dec3e736cd577c0d1d "
en-US-utf8.cfg	The string resource file. MD5 checksum is " c54e5e586988efd897c0f61b2e1a3477 "

Support Platforms:

Operation System Support

- Windows 7 32bit / 64bit
- Windows 8 32bit / 64bit
- Windows 8.1 32bit / 64bit
- Window 10 32bit / 64bit

Hardware Requirements

- Core i3 processor or above
- 2GB RAM or above
- 100MB free hard disk or above
- WXGA (Wide XGA 1280x800) and above display

Version:

Software Version: 2.1.5 C0

Enhanced Features:

1. **[GUI]** Support IPv6 address display (for switch firmware V4.70).

Bug Fix:

1. **[Vulnerability]** Fix vulnerability issue for CVE-2020-27667.

Known Issue:

1. **[ZON]** ZON utility V2.1.3 and lower versions are not compatible with GS1900 V2.50. Functions requiring password authentication will fail to authenticate due to previous ZON versions does not support GS1900 V2.50 password authentication algorithms.

Features:

- Quick search
- Set up IP configuration
- Renew devices' IP address (for DHCP mode only)
- Reboot devices
- Reset configuration to default
- Turn on devices' locator LED
- Change devices' web GUI
- Launch devices' web GUI
- Upgrade same model devices' firmware
- Launch ZAC with discovered AP(s)
- Import language files

Limitation of Settings:

- | | | |
|----|--|-------------|
| 1. | Length of system name | 64 |
| 2. | Length of location | 32 |
| 3. | Length of new administrator password | 32 |
| 4. | IPv4 address | Mandatory |
| 5. | Subnet mask | Mandatory |
| 6. | Administrator password | Mandatory |
| 7. | Discovered number of devices | 250 devices |
| 8. | [Firmware Upgrade] ZON only support one IP address on NIC card to do firmware upgrade. | |

9. [Firmware Upgrade] Firewall should disable when firmware upgrade.
10. [Firmware Upgrade] If device firmware upgraded fail, ZON doesn't have return error mechanism.

Support Models:

https://www.zyxel.com/form/zon_utility_download.shtml